



Product: SiS961/962/963 IDE Controller 5513

Date: 07/24/2002

Document Type: Release Note

Driver Ver.: 2.01a

SiS961/962/963 IDE Controller 5513 Driver [V2.01a]

1. Windows 2000 driver and Windows XP driver certified by WHQL as for logo driver.
2. Submission ID for Windows 2000 driver is 612212.
3. Submission ID for Windows XP driver is 609664.
4. IDE package update/Modification/Bug Fixed.
 - Fix the issue that IDE utility shows mode 5 when running in mode 6.
 - Fix the issue that HD information shows wrong type under 98/ME.
 - Fix the issue that setting hdinfo=0 is invalid in setup.ini.
 - Fix the issue that HCT ACPI crash.
 - Modify the default setting in setup.ini.
 - Add the Warning that can't remove previous IDE utility completely when using IDE driver v2.01a to uninstall SiS SCSI miniport driver or SiS mini IDE driver previous version.
 - Fix the issue that IDE utility shows wrong information on few of customer's motherboard.
 - Fix the issue that device manager shows PIO mode after taking BIOS ASL code off.
 - Fix the issue that IDE utility shows wrong version when updating new mini IDE driver.

5. Driver Version/Modification/Bug Fixed

[Windows 2000 driver v2.01a]

Filename	Driver Version
siside.sys	2.01.02.00

- Fix SiS962/SiS963 CD-RW and DVD-RW ROM Compatibility Issue.
- Support IDE 5518 install/uninstall.

[Windows XP driver v2.01a]

Filename	Driver Version
siside.sys	2.01.02.00

- Fix SiS962/SiS963 CD-RW and DVD-RW ROM Compatibility Issue.
- Support IDE 5518 install/uninstall.